

5. Cycles

| | | |
|-------|---|--------|
| 5.1 | G69 Measuring cycles | 5 - 2 |
| 5.2 | G71/G72/G73/G74/G75 Milling cycles | 5 - 16 |
| 5.2.1 | G71 Rectangular pocket roughing, conventional | 5 - 17 |
| 5.2.2 | G72 Rectangular pocket roughing, climb and conventional | 5 - 21 |
| 5.2.3 | G73 Rectangular pocket roughing and finishing | 5 - 25 |
| 5.2.4 | G74 circular pocket roughing | 5 - 29 |
| 5.2.5 | G75 circular pocket roughing and finishing | 5 - 33 |
| 5.3 | G80/G81/G83/G84/G85 Drilling cycles | 5 - 36 |
| 5.3.1 | G81 Drilling with return at rapid travers | 5 - 40 |
| 5.3.2 | G83 Deep-hole drilling | 5 - 42 |
| 5.3.3 | G83 Deep-hole drilling with degressive in-feed | 5 - 44 |
| 5.3.4 | G84 Tapping | 5 - 46 |
| 5.3.5 | G85 Drilling with retraction at feed rate | 5 - 48 |
| 5.4 | G86/G87/G88/G89 Drilling patterns | 5 - 50 |
| 5.4.1 | G86 Vector programming | 5 - 54 |
| 5.4.2 | G87 Parallelogram cycle | 5 - 60 |
| 5.4.3 | G88 Grid machining | 5 - 66 |
| 5.4.4 | G89 Machining of full circle and circular segment | 5 - 72 |
| 5.5 | Customer specific cycles | 5 - 80 |

5.1 G69 measuring cycles

General

The measuring cycle is a NC program with the term Z69. This cycle must like all other cycles into the NC memory be loaded. The measuring cycle is called with G69.

Measuring cycles use the parameters P140 to P160 for programming. These parameters contain two types of information:

- Data, e.g.. P141 safety margin
- Parameter numbers, which indicate, where the data are stored,
e.g.. P149: 500 (P149 is a pointer on another parameter).

Measuring cycles use the parameters P200 to P299 for internal calculations.
Parts it safely that only free parameters are used for the addressing of data fields.
Measuring cycles activate G40 (tool radius path correction out).

5.1 G69 measuring cycles (continued)**Measuring preparation**

- Connecting it the sensor with the measuring input on the AAZ module (15pol. HD Sub Socket).
If the measuring axes are distributed on several modules, all interconnect you Measuring inputs together (MT+ / MT-).
- Checking it the measuring logic for each measuring axis (P12045: \$xxxx1010...).
- Checking it the tool data of the used sensor. G69 requires tool length and tool radius of the sensor.

5.1 G69 measuring cycles (continued)

Compilation of the cycle parameters

| Parameter | meaning |
|--|---|
| P140 | cycle selection |
| P141 [mm] | safety margin |
| P143 [mm/min] | measuring speed |
| P144 [n] | number of measurements at the same point (> 0) |
| P147 (P147)+4 [mm] | pointer on the measuring tolerance data confidence range |
| P148 | measuring axis in plane system (1... 3) |
| P149 (P149)+0 [mm] (P149)+1 [mm] (P149)+2 [mm] (P149)+3 [mm] (P149)+4 [mm] (P149)+5 [mm] | pointer on the data of point of trigger XN, point of trigger in negative direction 1. axis XP, point of trigger in positive direction 1. axis YN, point of trigger in negative direction 2. axis YP, point of trigger in positive direction 2. axis ZN, point of trigger in negative direction 3. axis ZP, point of trigger in positive direction 3. axis |
| P150 (P150)+0 [mm] (P150)+1 [mm] (P150)+2 [mm] (P150)+3 [mm] | pointer on the calibration drilling data position of the calibration drilling focal point 1. axis (I) position of the calibration drilling focal point 2. axis (J) position of the calibration drilling focal point 3. axis (K) calibration drilling diameter |
| P152 [mm] | expected drilling diameter |
| P154 (P154)+0 [mm] (P154)+1 [mm] (P154)+2 [mm] | pointer on the measuring data measuring position 1. axis measuring position 2. axis measuring position 3. axis |

5.1 G69 measuring cycles (continued)

| Cycle | Parameter | Calibrate of the sensor in drilling | Calibrate of the sensor at area | Determining of centre a drilling | Determining of positions at area |
|---------------------------|-----------|-------------------------------------|---------------------------------|----------------------------------|----------------------------------|
| Cycle selection | P140 | 1 | 2 | 60 | 40 |
| Safety margin | P141 | x | x | x | x |
| Measuring speed | P143 | x | x | x | x |
| Number of measurem. | P144 | x | x | x | x |
| Measuring tolerance | P147 | x | x | x | x |
| Confidence range | (P147)+4 | x | x | x | x |
| Measuring axis in plane | P148 | | | | x |
| Data of point of trigger | P149 | x | x | x | x |
| Point of trigger XN | (P149)+0 | o | | x | x |
| Point of trigger XP | (P149)+1 | o | | x | x |
| Point of trigger YN | (P149)+2 | o | | x | x |
| Point of trigger YP | (P149)+3 | o | | x | x |
| Point of trigger ZN | (P149)+4 | | | | |
| Point of trigger ZP | (P149)+5 | | o | | x |
| Calibration drilling data | P150 | x | | | |
| Centre position 1.axis I | (P150)+0 | x** | x* | | |
| Centre position 1.axis J | (P150)+1 | x** | x* | | |
| Centre position 1.axis K | (P150)+2 | x** | x* | | |
| Drilling diameter | (P150)+3 | x | | | |
| Expected diameter | P152 | | | x | |
| Output data of the pos. | P154 | | | x | x |
| Measuring pos. 1. axis | (P154)+0 | | | o** | o* |
| Measuring pos. 2. axis | (P154)+1 | | | o** | o* |
| Measuring pos. 3. axis | (P154)+2 | | | o** | o* |

x: Parameter must be programmed
o: cycle edition

* : one of these
** : two of these

5.1 G69 measuring cycles (continued)

| Message | Meaning |
|---------|--|
| 8130 | uppersize |
| 8131 | undersize |
| 8132 | permissible measure difference exceeded |
| 8133 | confidence range exceeded |
| 8134 | reference drilling smaller than sensor |
| 8135 | boring axis is measuring axis |
| 8136 | sensor cannot be initiated |
| 8137 | P140 incorrectly programs |
| 8138 | P141 incorrectly programs |
| 8139 | P142 incorrectly programs |
| 8140 | P143 incorrectly programs |
| 8141 | P144 incorrectly programs |
| 8142 | P145/147/149/150 incorrectly programs |
| 8143 | empirical value incorrectly programs |
| 8144 | P146 incorrectly programs |
| 8145 | measuring tolerance 1 incorrectly programs |
| 8146 | measuring tolerance 2 incorrectly programs |
| 8147 | measuring tolerance 3 incorrectly programs |
| 8148 | measuring tolerance 4 incorrectly programs |
| 8149 | measuring tolerance 5 incorrectly programs |
| 8150 | P148 incorrectly programs |
| 8151 | point of trigger XN incorrectly programs |
| 8152 | point of trigger XP incorrectly programs |
| 8153 | point of trigger YN incorrectly programs |
| 8154 | point of trigger YP incorrectly programs |
| 8155 | point of trigger ZN incorrectly programs |
| 8156 | point of trigger ZP incorrectly programs |

5.1 G69 measuring cycles (continued)

| Message | Meaning |
|---------|--|
| 8157 | point of drilling I incorrectly programs |
| 8158 | point of drilling J incorrectly programs |
| 8159 | point of drilling K incorrectly programs |
| 8160 | point of drilling R incorrectly programs |
| 8161 | P151 incorrectly programs |
| 8162 | P152 incorrectly programs |
| 8163 | P153 incorrectly programs |
| 8164 | tool not called |
| 8165 | G53 not actively |
| 8166 | G54 to G59 not actively |
| 8167 | sensor actively outside of the safety area |
| 8168 | P154 incorrectly programs |

5.1 G69 measuring cycles (continued)

Calibration of the sensor in drilling G69 P140:1

The cycle requires a calibration drilling and a sensor. Measuring is executed with the two axes of the selected interpolation plane.

The sensor must be pre-positioned first on the drilling centre point in the selected interpolation plane and the sensor ball within the drilling.

If for example G17 is defined, the centre point of the calibration drilling must in (P150)+0 and (P150)+1 and the diameter in (P150)+3 to be defined.

The cycle positions first the 1. and 2. axis in the interpolation plane to the programmed centre point of the drilling. Now the cycle moves the 1. axis in positive direction to the drilling edge. The axis starts with the feed of the NC program and reduces the feed to F:p143 at the distance of P141 (safety margin) before the expected drilling edge. If a measuring signal before the safety margin occurs, a message is output (M8167).

From the safety margin the cycle moves the axis to the expected drilling edge plus confidence interval. If there is still no signal, a message (M8136) appears.

If there is a signal of the sensor, immediately the axis movement stops and the cycle calculates the point of trigger of the sensor and writes it in (P149)+n (axis movement positively: Point of trigger negatively).

If P144 is > 1, the cycle returns to the safety margin. From here the cycle starts a new measuring movement to the same drilling edge. Afterwards the cycle looks the other side up of the drilling. Become subsequently, the movements with the 2. Axis executed.

If the cycle is finished, then is the data field (P149)+n with the points of trigger of the sensor described. Following measuring cycles can operate with these data. The position of the moved axes now is in the center of the drilling.

Parts it safely,

- that the tool radius of the sensor is correct (P8160).
- to operate in the null point, in which the parameter data (P150) apply.

5.1 G69 measuring cycles (continued)

Example: The calibration of the sensor in drilling G69 P140:1

| | | | | | | | |
|------|-------------|------------|----|----------|----------|----------|-------------------------------|
| N20 | T1 | M16 | | | | | |
| N30 | G17 | G53 | G0 | X600.000 | Y300.000 | Z280.000 | A0 B0 |
| N40 | G1 | Z270 | | F3000 | | | |
| N100 | | | | | | | {Cycle G69 / 1 initialize } |
| N110 | P140:1 | | | | | | {Cycle type} |
| N120 | P141:3 | | | | | | {Safety margin } |
| N130 | P143:100 | | | | | | {Measuring speed } |
| N140 | P144:2 | | | | | | {Number of the measurements } |
| N150 | P147:500 | | | | | | {Pointer on tolerance data } |
| N160 | P504:5 | | | | | | {Confidence range } |
| N170 | P149:510 | | | | | | {Pointer on trigger data } |
| N180 | P150:520 | | | | | | {Pointer on measuring data } |
| N182 | P520:624.96 | P521:324.3 | | P523:54 | | | {I, J, D } |
| N230 | G69 | | | | | | {Cycle call } |
| N240 | G0 | Z280 | | M30 | | | |




Figure 5-1

5.1 G69 measuring cycles (continued)

Calibration of the sensor at area G69 P140:2

The cycle requires a calibration area and a sensor. Measuring becomes with the 3. axis of the selected interpolation plane executed (definition of G17...).

The sensor must be pre-positioned on the calibration area.

If for example G17 is defined, the position on the calibration area must in (P150)+2 to be defined.

The cycle moves now 3. axis toward the calibration area. The axis starts with the feed of the NC program and reduces the feed to F:p143 at the distance of P141 (safety margin) before the expected area. If a measuring signal before the safety margin occurs, a message is output (M8167).

From the safety margin the cycle moves the axis to the expected area plus confidence interval. If there is still no signal, a message (M8136) appears.

If there is a signal of the sensor, immediately the axis movement stops and the cycle calculates the point of trigger of the sensor and writes it in (P149)+n (axis movement positively: Point of trigger negatively).

If P144 is > 1, the cycle turns back to the safety margin. From here the cycle starts a new measuring movement to the same area.

If the cycle is finished, then is the data field (P149)+n with the points of trigger of the sensor described. Following measuring cycles can operate with these data. The position of the moved axis now is in the safety margin.

Parts it safely,

- that the tool radius of the sensor is correct (P8160, P8162).
- to operate in the null point, in which the parameter data (P150) apply.

5.1 G69 measuring cycles (continued)

Example: The calibration of the sensor in drilling G69 P140:2

| | | |
|------|-------------|----------------------------------|
| N20 | T1 M16 | |
| N30 | G17 G53 G0 | X600.000 Y300.000 Z280.000 A0 B0 |
| N40 | G1 Z270 | F3000 |
| N100 | | {Cycle G69 / 2 initialize } |
| N110 | P140:2 | {Cycle type} |
| N120 | P141:3 | {Safety margin } |
| N130 | P143:100 | {Measuring speed } |
| N140 | P144:2 | {Number of the measurements } |
| N150 | P147:500 | {Pointer on tolerance data } |
| N160 | P504:5 | {Confidence range } |
| N170 | P149:510 | {Pointer on trigger data } |
| N180 | P150:520 | {Pointer on measuring data } |
| N182 | P522:260.20 | {K } |
| N230 | G69 | {Cycle call } |
| N240 | G0 Z280 | M30 |




Figure 5-2

5.1 G69 measuring cycles (continued)

Determining the center of a drilling G69 P140:60

The measurement is executed with both axes of the selected interpolation plane (see G17...). The sensor should be at the beginning approximately on the drilling centre point in the selected interpolation plane and the sensor ball within the drilling pre-positioned.

The cycle moves the 1. axis in positive direction to the drilling edge. The axis starts with the feed of the NC program and reduces the feed to F:p143 at the distance $(\text{diameters} / 2 - \text{safety margin}) = (P152 / 2 - P141)$.

If a measuring signal before this point occurs, a message is output (M8167).

From here the cycle moves the axis to the expected drilling edge plus confidence interval. If there is still no signal, a message (M8136) appears.

If there is a signal of the sensor, immediately the axis movement stops and the cycle calculates the edge position.

If P144 is > 1 , the cycle turns back to the safety margin. From here the cycle starts a new measuring movement to the same drilling edge. Afterwards the cycle looks the other side up of the drilling. Now become the movements with the 2. axis made.

If the cycle is finished, then is the data field (P154)+n with the drilling centre point described. The position of the moved axes now is in the center of the drilling.

Parts it safely that the tool radius of the sensor is correct (P8161, P8163).

5.1 G69 measuring cycles (continued)

Example: The calibration of the sensor in drilling G69 P140:60

| | | |
|------|------------|----------------------------------|
| N20 | T1 M16 | |
| N30 | G17 G53 G0 | X600.000 Y300.000 Z280.000 A0 B0 |
| N40 | G1 Z270 | F3000 |
| N100 | | {Cycle G69 / 60 initialize } |
| N110 | P140:60 | {Cycle type} |
| N120 | P141:3 | {Safety margin } |
| N130 | P143:100 | {Measuring speed } |
| N140 | P144:2 | {Number of the measurements } |
| N150 | P147:500 | {Pointer on tolerance data } |
| N160 | P504:5 | {Confidence range } |
| N170 | P149:510 | {Pointer on trigger data } |
| N180 | P150:520 | {Pointer on measuring data } |
| N182 | P154:530 | {Pointer on output } |
| N230 | G69 | {Cycle call } |
| N240 | G0 Z280 | M30 |




Figure 5-3

5.1 G69 measuring cycles (continued)

determining an individual item in the area G69 P140:40

The sensor must be pre-positioned at the beginning over the contact surface.
The measurement is executed with the axis defined in P148.

The cycle starts into negative direction with measuring speed (P143)
If there is still no signal of the sensor, the axes in the position (initial position - confidence interval (P147)+4) stop and a message (M8136) appears.

If there is a signal of the sensor, immediately the axis movement stops and the cycle calculates the position on the area and writes the data in (P154)+n.

| | | | |
|-------------|-------------|--------------------|----------|
| Example G17 | with P148:3 | writes after cycle | P(154)+2 |
| | with P148:2 | writes after cycle | P(154)+1 |
| | with P148:1 | writes after cycle | P(154)+0 |

If P144 is > 1, the cycle turns back to the safety margin. From here the cycle starts a new measuring movement to the same area.

The position of the moved axes is in the safety margin.

Parts it safely,

- that the tool length of the sensor is correct (P8161, P8163),
if 3. axis is selected
- that the tool radius of the sensor is correct (P8160, P8162),
if 1. or 2. axis is selected

5.1 G69 measuring cycles (continued)

Example: The calibration of the sensor in drilling G69 P140:40

| | | |
|------|------------|----------------------------------|
| N20 | T1 M16 | |
| N30 | G17 G53 G0 | X600.000 Y300.000 Z280.000 A0 B0 |
| N40 | G1 Z270 | F3000 |
| N100 | | {Cycle G69 / 40 initialize } |
| N110 | P140:40 | {Cycle type} |
| N120 | P141:3 | {Safety margin } |
| N130 | P143:100 | {Measuring speed } |
| N140 | P144:2 | {Number of the measurements } |
| N150 | P147:500 | {Pointer on tolerance data } |
| N160 | P504:5 | {Confidence range } |
| N170 | P144:3 | {Measuring axes } |
| N180 | P149:510 | {Pointer on trigger data } |
| N182 | P150:520 | {Pointer on measuring data } |
| N230 | G69 | {Cycle call } |
| N240 | G0 Z280 | M30 |




Figure 5-4

5.2 G71 / G72 / G73 / G74 / G75 Milling cycles**List of canned milling cycles**

G71 Rectangular pocket roughing, conventional
G72 Rectangular pocket roughing, conventional and climb
G73 Rectangular pocket roughing and finishing
G74 Circular pocket roughing
G75 Circular pocket roughing and finishing

The millinging cycles are block by block effective.
The parameter inputs remain against it modal effectively.

In order to avoid over regulation, all parameters are to be reset,
with a programming type not to be used.

Messages

The numbers for cycle messages start with 8xxx.
A list can be found in section messages

5.2.1 G71 Rectangular pocket roughing, conventional

Starting point definition

Before starting any machining cycles, the milling cutter should be above the workpiece by the safety margin and at the centre of the pocket.

Whether the starting point S1 or S2 is homed into depends on the sign of the programmed in-feed P16.

Positive sign: starting point S1

Negative sign: starting point S2

The milling direction is established by the CNC and always in the direction of the longer pocket side. If the pocket sides are the same, milling takes place in the X direction.

Parameter input

All parameters except for P16 should have positive sign when inputting.

| Parameter | Significance |
|-----------|--------------|
|-----------|--------------|

| | |
|-----|--|
| P11 | Pocket dimension in X direction |
| P12 | Pocket dimension in Y direction |
| P13 | Pocket depth in Z direction |
| P14 | Corner radius |
| P15 | Contour allowance in X and Y directions |
| P16 | In-feed dimension in X or Y directions (prefix + or -) |
| P17 | In-feed dimension in Z direction |
| P18 | Pocket depth allowance in Z direction |
| P19 | Safety margin in Z direction |
| P21 | Feed rate in Z direction (when plunging into material) |

During cycle processing a possibly programmed correction becomes G41 / G42 switched off, since the tool radius correction in the cycle is considered.

Feed in z-direction (only when immersing into the material) is programmable with P21.

Is P21 programmed, does not become immersing into the material with under F programmed feed executed.

5.2.1 G71 Rectangular pocket roughing, conventional (continued)

Machining sequence

- Home in on starting point S1 or S2 (depending on prefix of P16)
- In-feed in Z direction at feed rate P21 (if programmed)
- Conventional milling to pocket dimension less allowance P15 in X and Y directions
- Retraction of milling cutter by 2 mm in Z direction
- Retraction in X or Y direction
- In-feed in Z direction
- In-feed in X or Y direction
- In-feed repetition until pocket dimension less allowance P15 is reached
- Milling over burrs
- Retraction in Z direction to safety margin
- Retraction to starting position in XY plane
- Repetition of in-feeds until pocket depth less allowance P18 is reached
- Retraction to starting position (centre of pocket)




Figure 5-5

5.2.1 G71 Rectangular pocket roughing, conventional (continued)

G 71 Example 1: Pocket dimensions X=71mm, Y=41mm, Z=5mm; Tool-radius=3mm

| | | | | | | | |
|-----|--------|-------|-------|-------|--------|---------|-------------|
| N10 | G00 | G54 | G90 | F2500 | S900 | T02 | M06 M03 M07 |
| N20 | G71 | X55,5 | Y40,5 | Z2 | P11:71 | P12:41 | P13:5 |
| | P14:-- | P15:0 | P16:4 | P17:3 | P19:2 | P21:100 | M30 |




Figure 5-6

Parameters:

P11, P12, P13 Pocket dimensions in X, Y, Z direction

P16, P17 In-feed in Y, Z direction

P19 Safety margin in Z direction

P21 Feed rate in Z direction

Run:

Block 10 Zero point, absolute dimension, feed rate, spindle, tool

Block 20 Cycle call-up, positioning on centre of pocket X, Y, Z, pocket dimensions P11, P12, P13, in-feed dimensions P16, P17, safety margin P19

Remarks:

Since the corner radius P14 is not programmed, it becomes with the programmed tool radius equated.

5.2.1 G71 Rectangular pocket roughing, conventional (continued)

G71 Example 2: Pocket dimensions X=46mm, Y=81mm, Z=30mm;
Tool-radius=3mm, corner radius=13mm

| | | | | | | |
|-----|--------|--------|-------|-------|---------|-----------------|
| N10 | G00 | G54 | G90 | F1000 | S750 | T02 M06 M03 M07 |
| N20 | G71 | X43 | Y60,5 | Z1 | P11:46 | P12:81 |
| | P14:13 | P16:-4 | P17:7 | P19:1 | P21:400 | P13:30 |
| | | | | | | M30 |




Figure 5-7

Parameters:

| | |
|---------------|--|
| P11, P12, P13 | Pocket dimensions in X, Y, Z direction |
| P14 | Corner radius |
| P16, P17 | In-feed in X, Z direction |
| P19 | Safety margin in Z direction |
| P21 | Feed rate in Z direction |

Run:

| | |
|----------|--|
| Block 10 | Zero point, absolute dimension, feed rate, spindle, tool |
| Block 20 | Cycle call-up, positioning on centre of pocket X, Y, Z; pocket dimensions P11, P12, P13, in-feed dimensions P16, P17, corner radius P14, safety margin P19 |

Remarks: If P14 = 0 is or smaller than the tool radius, then becomes after that start clearing the program execution stopped and message 8001 indicated.

5.2.2 G72 Rectangular pocket roughing, climb and conventional

Starting point definition

Before the start of the machining cycles the milling cutter should be above the workpiece by the safety margin and in the middle of the pocket.

Whether the starting point S1 or S2 is homed into depends on the sign of the programmed in-feed P16.

Sign, positive: starting point S1

Sign, negative: starting point S2

The determination of the milling direction takes place in the CNC and always in the direction of the longer pocket side. If the pocket sides are the same, milling takes place along the X direction.

Parameter input

All parameters except for P16 should have a positive sign during inputting.

| Parameter | Significance |
|-----------|--|
| P11 | Pocket dimension in X direction |
| P12 | Pocket dimension in Y direction |
| P13 | Pocket depth in Z direction |
| P14 | Corner radius |
| P15 | Contour allowance in X and Y directions |
| P16 | In-feed dimension in X or Y directions (sign +/-) |
| P17 | In-feed dimension in Z direction |
| P18 | Pocket depth allowance in Z direction |
| P19 | Safety margin in Z direction |
| P21 | Feed rate in Z direction (when plunging into material) |

5.2.2 G72 Rectangular pocket roughing, climb and conventional (continued)

Machining sequence

- Home in on starting point S1 or S2 (each according to sign of P16)
- In-feed in Z direction at feed rate P21 (if programmed)
- Conventional milling to pocket dimension less the allowance P15 in X and Y direction
- In-feed in X or Y direction
- Milling in conventional direction
- In-feed in X or Y direction
- In-feed repetition until pocket dimension less allowance P15 is reached
- Milling over burrs along edge
- Retraction in Z direction to safety margin
- Retraction to starting position in XY plane
- In-feed in Z direction to previous dimension
- Milling over burrs along other edge
- Retraction in Z direction to safety margin
- Retraction to starting position in XY plane
- Repetition of in-feeds until pocket depth less allowance P18 is reached
- Retraction to starting position (centre of pocket)




Figure 5-8

5.2.2 G72 Rectangular pocket roughing, climb and conventional milling (cont.)

G72 Example 1: Pocket dimensions X=66mm, Y=31mm, Z=5mm; Tool-radius=3mm

```

N10 G00 G54 G90      F2000      S850      T02      M06 M03 M07
N20 G72 X53 Y35,5    Z1        P11:66  P12:31  P13:5   P14:--  P15:0
      P16:5,1  P17:3    P19:1    M30
  
```




Figure 5-9

Parameters:

P11, P12, P13 Pocket dimensions in X, Y, Z direction

P16, P17 In-feed in Y, Z direction

P19 Safety margin in Z direction

Run: Block 10 Zero point, absolute dimension, feed rate, spindle, tool
 Block 20 Cycle call-up, positioning on centre of pocket X, Y, Z; pocket dimensions P11, P12, P13, in-feed dimensions P16, P17, safety margin P19

Remarks: As the corner radius P14 is not programmed it is identified along with the programmed tool radius.

5.2.2 G72 Rectangular pocket roughing, climb and conventional milling (cont.)

G72 Example 2: Pocket dimensions X=44mm, Y=69mm, Z=3mm; Tool radius=3mm, corner radius=15mm

| | | | | | | | | | |
|-----|-----|---------|-------|-------|---------|--------|-------|--------|-------|
| N10 | G00 | G54 | G90 | F2000 | S950 | T02 | M06 | M03 | M07 |
| N20 | G72 | X42 | Y54,5 | Z1 | P11:44 | P12:69 | P13:3 | P14:15 | P15=0 |
| | | P16:5,5 | P17:3 | P19:1 | P21:100 | M30 | | | |




Figure 5-110

Parameters:

| | |
|---------------|--|
| P11, P12, P13 | Pocket dimensions in X, Y, Z direction |
| P14 | Corner radius |
| P16, P17 | In-feed in X, Z direction |
| P19 | Safety margin in Z direction |
| P21 | Feed rate in Z direction |

| | | |
|------|----------|--|
| Run: | Block 10 | Zero point, absolute dimension, feed rate, spindle, tool |
| | Block 20 | Cycle call-up, positioning on centre of pocket X, Y, Z; pocket dimensions P11, P12, P13, in-feed dimensions P16, P17, corner radius P14, safety margin P19 |

Remarks: If P14=0 or is smaller than the tool radius the program run is shut down after the start and fault feed-back 1301 (geometry fault) is displayed.

5.2.3 G73 Rectangular pocket roughing and finishing

Starting point definition

Before the start of the machining cycles, the milling cutter should be above the workpiece at the safety margin and in the middle of the pocket.

Whether the starting point S1 or S2 is homed into depends on the sign of the programmed in-feed P16.

Sign, positive: starting point S1

Sign, negative: starting point S2

The milling direction is established in the CNC and is always in the direction of the longer pocket side. If the pocket sides are the same, milling takes place along the X direction.

Parameter input

All parameters except for P16 should have a positive sign when inputting.

| Parameter | Significance |
|-----------|--------------|
|-----------|--------------|

| | |
|-----|--|
| P11 | Pocket dimension in X direction |
| P12 | Pocket dimension in Y direction |
| P13 | Pocket depth in Z direction |
| P14 | Corner radius |
| P15 | Contour allowance in X and Y direction |
| P16 | In-feed dimension in X or Y direction (sign +/-) |
| P17 | In-feed dimension in Z direction |
| P18 | Pocket depth allowance in Z direction |
| P19 | Safety margin in Z direction |
| P20 | In-feed dimension when finishing, to remove allowance P15; In-feed direction as for P16 |
| P21 | Feed rate in Z direction (when plunging into material) |

5.2.3 G73 Rectangular pocket roughing and finishing (continued)

Machining

- Home in on starting point S1 or S2 (each according to sign of P16)
- In-feed in Z direction at feed rate P21 (if programmed)
- Milling pocket contour (less allowance P15) to starting point
- In-feed repetition until pocket depth P13 less allowance P18 is reached
- Retraction to starting plane
- In-feed in X or Y direction
- In-feed in Z direction at feed rate P21 (if programmed)
- Conventional and climb milling of remaining material
- Retraction in Z direction and to starting position and in-feed
- In-feed repetition until pocket dimension less allowance P18 is reached.
- Retraction in Z direction to starting plane
- In-feed for finishing
- In-feed in Z direction at 0.5 of the programmed feed rate F to pocket depth less P18
- Finishing contour to starting point at 0.5 of the programmed feed rate
- In-feed repetition until finished contour is reached
- Retraction to starting position at programmed feed rate




Figure 5-11

5.2.3 G73 Rectangular pocket roughing and finishing (continued)

G73 Example 1: Pocket dimensions X=64mm, Y=35mm, Z=5mm; Tool radius=3mm

```

N10 G00 G54      G90      F1500      S950      T02      M06      M03      M07
N20 G73 X52,5    Y37,5    Z1          P11:64    P12:35    P13:5    P14=0
      P15:1      P16:4,5    P17:2      P19:1      P20:1      M30
  
```




Figure 5-12

Parameters:

| | |
|---------------|--|
| P11, P12, P13 | Pocket dimensions in X, Y, Z direction |
| P15 | Allowance in X and Y direction |
| P16, P17 | In-feed in Y, Z direction |
| P19 | Safety margin in Z direction |
| P20 | Allowance during finishing |

| | | |
|------|----------|--|
| Run: | Block 10 | Zero point, absolute dimension, feed rate, spindle, tool |
| | Block 20 | Cycle call-up, positioning on centre of pocket X, Y, Z; pocket dimensions P11, P12, P13, in-feed dimensions P16, P17, allowance P15, safety margin P19, in-feed dimension when finishing P20 |

Remarks: As the corner radius P14 is not programmed it is made equal to the programmed tool radius.

5.2.3 G73 Rectangular pocket roughing and finishing (continued)

G73 Example 2: Pocket dimensions X=65mm, Y=35mm, Z=5mm; Tool radius=3mm, corner radius=11mm

| | | | | | | | | | |
|-----|-----|---------|---------|-------|--------|--------|-------|--------|-----|
| N10 | G00 | G54 | G90 | F1500 | S950 | T02 | M06 | M03 | M07 |
| N20 | G73 | X52,5 | Y37,5 | Z1 | P11:65 | P12:35 | P13:5 | P14:11 | |
| | | P15:1,5 | P16:4,2 | P17:2 | P19:1 | P20:1 | M30 | | |




Figure 5-13

Parameters:

| | |
|---------------|--|
| P11, P12, P13 | Pocket dimensions in X, Y, Z direction |
| P14 | Corner radius |
| P15 | Allowance in X and Y direction |
| P16, P17 | In-feed in Y, Z direction |
| P19 | Safety margin in Z direction |
| P20 | Allowance during finishing |

Run:

| | |
|----------|--|
| Block 10 | Zero point, absolute dimension, feed rate, spindle, tool |
| Block 20 | Cycle call-up, positioning on centre of pocket X, Y, Z; pocket dimensions P11, P12, P13, in-feed dimensions P16, P17, corner radius P14, safety margin P19, allowance P15, infeed dimension during finishing P20 |

Remarks: If P14=0 or is smaller than the tool radius the program run is shut down after the start and message 1301 (geometry fault) is displayed.

5.2.4 G74 circular pocket roughing

Starting point definition

Before the start of the machining cycles the milling cutter should be above the workpiece at the safety margin and at the centre of the pocket.

Parameter input

All parameters except for P16 should have a positive sign when inputting. The sign of P16 determines the direction of milling, i.e.:

Milling direction G02, the sign of P16 is positive

Milling direction G03, the sign of P16 is negative

| Parameter | Significance |
|-----------|--------------|
|-----------|--------------|

| | |
|-----|--|
| P11 | Internal radius (if core drilled) |
| P12 | Depth of pocket |
| P14 | Pocket radius |
| P15 | Allowance at circumference |
| P16 | In-feed dimension in X direction |
| P17 | In-feed dimension in Z direction |
| P18 | Pocket depth allowance in Z direction |
| P19 | Safety margin |
| P21 | Feed rate in Z direction (when plunging into material) |

When specifying the internal radius P11, the first in-feed in the X direction is corrected by the appropriate amount: 1st in-feed = P11 + P16.

5.2.4 G74 circular pocket roughing (continued)

Machining

- In-feed in Z direction at feed rate P21 (if programmed)
- In-feed in X direction
- Spiral milling
- Milling circular pocket to finished size less allowance P15
- Retraction along the semicircle with $R=2.5\text{mm}$ max.
- Retraction in Z direction by 2mm
- Retraction to centre of pocket
- In-feed repetition until pocket dimension less allowance P18 in Z direction is reached
- Retraction to starting position




Figure 5-14

5.2.4 G74 Circular pocket roughing (continued)

G74 Example 1: Pocket radius R=33mm, pocket depth Z=27mm; Tool radius=3mm

```

N10 G00 G54 G90 F1500 S950 T02 M06 M03 M07
N20 G74 X53 Y53 Z1 P13:27 P14:33 P16:5,1 P17:5 P19:1 M30

```




Figure 5-15

Parameters:

P13 Pocket depth in Z direction
 P16, P17 In-feed in X, Z direction
 P14 Pocket radius
 P19 Safety margin in Z direction

Run: Block 10 Zero point, absolute dimension, feed rate, spindle, tool
 Block 20 Cycle call-up, positioning on centre of pocket X, Y, Z, pocket depth P13, in-feed dimensions P16, P17, pocket radius P14, safety margin P19

5.2.4 G74 circular pocket roughing (continued)

G74 Example 2: Pocket radius R=30mm, pocket depth Z=31mm; Tool radius=3mm, core bore drilling at 20mm dia.

| | | | | | | | | | |
|-----|-----|-------|-----|-------|--------|--------|--------|-------|-------|
| N10 | G00 | G54 | G90 | F1500 | S950 | T02 | M06 | M03 | M07 |
| N20 | G74 | X50 | Y50 | Z1 | P11:10 | P13:31 | P14:30 | P16:4 | P17:8 |
| | | P19:1 | M30 | | | | | | |




Figure 5-16

Parameters:

| | |
|----------|-----------------------------------|
| P11 | Internal radius (if core drilled) |
| P13 | Pocket depth in Z direction |
| P16, P17 | In-feed in X, Z direction |
| P14 | Pocket radius |
| P19 | Safety margin in Z direction |

| | | |
|------|----------|---|
| Run: | Block 10 | Zero point, absolute dimension, feed rate, spindle, tool |
| | Block 20 | Cycle call-up, positioning on centre of pocket X, Y, Z, pocket depth P13, in-feed dimensions P16, P17, pocket radius P14, safety margin P19 |

5.2.5 G75 circular pocket roughing and finishing

Starting point definition

Before the start of the machining cycles the milling cutter should be above the workpiece at the safety margin and at the centre of the pocket.

Parameter input

All parameters except for P16 should have a positive sign when inputting. The sign of P16 determines the direction of milling, i.e.:

Milling direction G02, the sign of P16 is positive

Milling direction G03, the sign of P16 is negative

| Parameter | Significance |
|-----------|--|
| P11 | Internal radius (if drilled) |
| P13 | Depth of pocket |
| P14 | Pocket radius |
| P15 | Allowance at circumference |
| P16 | In-feed dimension in X direction |
| P17 | In-feed dimension in Z direction |
| P18 | Pocket depth allowance in Z direction |
| P19 | Safety margin |
| P20 | In-feed dimension when finishing, to remove P15, in-feed direction as with P16 |
| P21 | Feed rate in Z direction (when plunging into material) |

With specification of the internal radius P11 the first feed in x-direction becomes around the suitable amount corrects: 1. $\text{Feed} = P11 + P16$.

5.2.5 G75 circular pocket roughing and finishing (continued)

Machining

- In-feed in Z direction at feed rate P21 (if programmed)
- In-feed in X direction
- Spiral milling
- Milling circular pocket to finished size less allowance P15
- Retraction along the semicircle with $R=2.5\text{mm}$ max.
- Retraction in Z direction
- Retraction to centre of pocket
- In-feed repetition until pocket dimension less allowance P18 in Z direction is reached
- Retraction along the semicircle with $R=2.5\text{mm}$ max.
- In-feed at half feed rate for finishing along the semicircle
- Milling along the circle at half of the programmed feed rate
- Retraction along the semicircle
- In-feed repetition until finished dimension is reached
- Retraction along the semicircle
- Retraction to starting position at programmed feed rate




Figure 5-17

5.2.5 G75 circular pocket roughing and finishing (continued)

G75 Example 1: Pocket radius R=28mm, pocket depth Z=35mm; Tool radius=3mm

```

N10 G00 G54 G90 F1500 S950 T02 M06 M03 M07
N20 G75 X48 Y48 Z1 P13:35 P14:28 P15:2 P16:4,1 P17:8
      P19:1 P20:2 M30

```




Figure 5-18

Parameters:

P13 Pocket depth in Z direction
 P14 Pocket radius
 P15 Allowance at circumference
 P16, P17 In-feed in X, Z direction
 P19 Safety margin in Z direction
 P20 In-feed dimension during finishing

Run: Block 10 Zero point, absolute dimension, feed rate, spindle, tool
 Block 20 Cycle call-up, positioning on centre of pocket X, Y, Z, pocket depth P13, in-feed dimensions P16, P17, pocket radius P14, safety margin P19, in-feed dimension during finishing P20

5.3 G80 / G81 / G83 / G84 / G85 Drilling cycles

the drilling cycle functions G81 / G83 / G84 / G85 operate modally and overwrite each other mutually. G80 clears all drilling cycles resulting in G00 (rapid traverse) and G64 (clearing feed rate 100%) becoming effective automatically.

G80 is automatically set at the program start.

List of drilling cycles

| Drilling cycle according to DIN 66025 | Programming in CNC900 |
|---|---|
| G81 Drilling with rapid return | G81 |
| G82 Drilling with rapid return and | G81, G04. Free cutting time free-cutting |
| G83 Deep hole drilling | G83 |
| G84 Tapping | G84, G04. Spindle turnaround time |
| G85 Drilling with return at feed rate | G85 |
| G86 Drilling with rapid return, free cutting and spindle „off“ | G81, G04. Free cutting time, M05 |
| G87 Drilling with manual return | - |
| G88 Drilling with manual return and free cutting | - |
| G89 Drilling with return at feed rate and | G85, G04. Free cutting time Further possibilities with the CNC900, e.g.: G83, G04. Free cutting time G83, G04. Free cutting time, M05 |

5.3 G80 / G81 / G83 / G84 / G85 Drilling cycles

Programming of characteristics

for the programming of the drill cycles only parameters can be used.

Parameter Meaning

| | | | |
|-----|--------------------|---|-------------|
| P30 | Free cutting time | Turn back time of the spindle after achieving the drilling depth | |
| P31 | Compensating chuck | G84 P31 : 3 = thread cutting without compensating chuck right P31 : 4 = thread cutting without compensating chuck left P31 : 0 or - = G84 standard cycle (with compensating chuck) | |
| P32 | Drilling feed | | |
| P32 | Thread pitch | bei G84 | |
| P33 | Drilling depth | | absolute |
| P33 | Thread depth | bei G84 | absolute |
| P34 | Anticipation plane | Safety margin of the processing upper edge | absolute |
| P35 | Retreat plane | To run around of obstacles in the setting axis | absolute |
| P36 | No. of strokes | G83, constant setting depth = $(P33 - P34) / P36$ | |
| P36 | Setting depth | G83, degressive setting depth | |
| P37 | 1st Stroke | G83, degressive setting depth | |
| P38 | Safety margin | G83, presetting = 1mm | incremental |
| P39 | Gradual decrease | G83, degressive setting depth P39 : 1 = on P39 : 0 or - = off | |

Drilling depth P33, anticipation plane P34 and retreat plane P35 are dependant of the planes set over G17, G18 or G19. In the following examples, G17 is activated with the axis names X (1st axis), Y (2nd axis) and Z (3rd axis).

5.3 G80 / G81 / G83 / G84 / G85 Drilling cycles (continued)

Parameters for drilling cycles

| Drilling cycle | Parameter | Free cutting time | Drilling feed | Drilling depth | Anticipation plane | Retreat plane | Number of strokes | 1st stroke | Safety margin | Gradual decrease | Drilling speed |
|----------------|-----------|-------------------|---------------|----------------|--------------------|---------------|-------------------|------------|---------------|------------------|----------------|
| | | P30 | P32 | P33 | P43 | P35 | P36 | P37 | P38 | P39 | S |
| G81 | | * | * | * | * | * | - | - | - | - | * |
| G83 constant | | * | * | * | * | * | * | - | * | - | * |
| G83 degressiv | | * | * | * | * | * | * | * | * | * | * |
| G84 | | * | * | * | * | * | - | - | - | - | * |
| G85 | | * | * | * | * | * | - | - | - | - | * |

When calling up a drilling cycle, a direction of spindle rotation and spindle speed should be active. If these two values have already been set when the cycle is called up they are taken as the preset values for the drilling cycles.

Programming of a safety margin (P38) is optional. If this characteristic is not input a safety margin of 1 mm is preset.

When calling up a drilling cycle, the fields marked * should have been programmed in one way or another.

Messages

The numbers for cycle messages start with 8xxx.
A list can be found in section messages

Activation conditions

For a drilling cycle to be carried out, at least one of the X, Y or Z coordinates should be programmed per main block. This also applies to parameter P33 for the drilling depth Z.

5.3 G80 / G81 / G83 / G84 / G85 Drilling cycles (continued)**Positioning speed**

The pre-positioning of the axes takes place at rapid traverse. When using polar coordinates programming with interpolation mode G02 or G03 set, positioning is at the programmed feed rate. It is therefore good policy to specify the feed rate with parameter P32.

Effect of G91 incremental dimensions

Using incremental dimensions, the positioning axes (XY with G17, ZX with G18, YZ with G19) are traversed in incremental mode. The specified coordinates are always taken as absolute for the characteristics (Z, R, K).

Effect of G66

A programmed G66 is effective throughout the complete drilling cycle.


Effect of G63/G64

The function, when set, is retained throughout the complete drilling cycle. The tapping cycle G84 automatically sets G63 for period of the in-feed traverse.

Effect of other additional functions

Other additional functions are effective in a block with travel information (cycle is executed) before or after the travels that are defined in the cycle.

5.3.1 G81 Drilling with return at rapid travers

**Meaning of the parameters**

| | | |
|-----|--------------------|--|
| P30 | Free cutting time | Turn back time of the spindle after achieving the drilling depth |
| P32 | Drilling feed | |
| P33 | Drilling depth | |
| P34 | Anticipation plane | Safety margin of the processing upper edge |
| P35 | Retreat plane | To go around of obstacles in the setting axis |

5.3.1 G81 Drilling with return at rapid travers (continued)

Example

```
N20 G56 G00      X0  Y0  Z100      S1200      F1500      M03      T01  M16
N30 G81 Z80      P30:1      P32:800  P33:0      P34:32      P35:60
N40 M05 ...
```

Sequence plan

- 1 Switch on spindle (M03, M04) and position X and Y axis in rapid traverse.
- 2 After reaching the X and Y position, position the Z axis to the anticipation plane (P34) in rapid traverse.
- 3 After reaching the anticipation plane the Z axis is traversed at working feed rate (P32) to the drilling depth (P33).
- 4 After reaching the drilling depth any possibly programmed free cutting time (P30) is awaited.
- 5 After it the Z-axis in rapid traverse moves on the retreat plane (P35) and afterwards the spindle is switched off (M05).

5.3.2 G83 Deep-hole drilling with constant setting depth

If the parameter P39:0 or is not programmed, the programmed drilling depth (P33) by repeated constant setting depth of the active drilling depth is achieved.

The active drilling depth is $(P33 - P34) * n / P36$, however $n = 1, 2, ..$ (settin depth = stroke) is.




Figure 5-20

Meaning of the parameters

| | | |
|-----|--------------------|--|
| P30 | Free cutting time | Turn back time of the spindle after achieving the drilling depth |
| P32 | Drilling feed | |
| P33 | Drilling depth | |
| P34 | Anticipation plane | Safety margin of the processing upper edge |
| P35 | Retreat plane | To go around of obstacles in the setting axis |
| P36 | No. of strokes | constant setting depth = $(P33 - P34) / P36$ |
| P38 | Safety margin | presetting = 1mm |
| P39 | Gradual decrease | 0 or - = off |

5.3.2 G83 Deep-hole drilling with constant setting depth (continued)

Example

```
N20 G56 G00      X0  Y0  Z100      S1200      F1500      M03      T01 M16
N30 G83 Z80 P30:1 P32:800 P33:0 P34:48 P35:60 P36:3 P38:1 P39:0
N40 M05 ...
```

Sequence plan

- 1 Switch spindle on (M03, M04) and X and Y axis in rapid traverse position.
- 2 After achieving the X and Y position the Z-axis runs in rapid traverse on those anticipation plane (P34).
- 3 After achieving the anticipation plane (P34) the Z axis with working feed moves (P32) to the 1. drilling depth ($P34 + ((P33 - P34) * 1 / P36)$).
- 4 After achieving the 1. drilling path the Z axis drives back in rapid traverse up to the anticipation plane.
- 5 From the anticipation plane the Z axis drives afterwards in rapid traverse up to the 1. drilling depth plus safety margin ($P34 + ((P33 - P34) * 1 / P36) + P38$).
- 6 The Z axis induces itself with working feed (P32) to 2. drilling depth ($P34 + ((P33 - P34) * 2 / P36)$).
- 7 After achieving the 2. drilling depth the Z axis drives back in rapid traverse up to the anticipation plane.
- 8 From the anticipation plane the Z-axis drives afterwards in rapid traverse up to the 2. drilling depth plus safety margin ($P34 + ((P33 - P34) * 2 / P36) + P38$).
- 9 The Z axis induces itself with working feed (P32) to the 3. drilling depth etc. to P33.
- 10 With the achieving of the drilling depth (P33) a programmed free cutting time (P30) becomes been waiting.
- 11 Afterwards the Z axis in rapid traverse moves back on the retreat plane (P35) and afterwards the spindle is switched off (M05).

5.3.3 G83 Deep-hole drilling with degressive setting depth

If the parameter P39:1 is programmed (the input value is not determining), the programmed drilling depth (P33) by repeated, reduced setting depth (gradual decrease) of the active drilling depth is achieved.

The active drilling depth is $P37 - (n-1) \cdot P36$, whereby $n=1, 2, \dots$ is (nth setting depth = stroke).
If $P37 - (n-1) \cdot P36 \leq P36$, the active drilling depth = P36 is set.

Before each setting depth checked, whether two setting depths (drilling depth calculated + P36 (gradual decrease measure)) still feasible are. If not, then the new drilling depth calculated by remainder path / 2 and executed the final two setting depths with this value.




Figure 5-21

Meaning of the parameters

| | | |
|-----|--------------------|--|
| P32 | drilling feed | |
| P33 | drilling depth | |
| P34 | anticipation plane | safety margin of the processing upper edge |
| P35 | retreat plane | to the run around of obstacles in the setting axis |
| P36 | setting depth | degressive setting depth |
| P37 | 1. stroke | degressive setting depth |
| P38 | safety margin | presetting = 1mm |
| P39 | gradual decrease | degressive setting depth |
| | | 1 = on |

5.3.3 G83 Deep-hole drilling with degressive setting depth (continued)

Example

```
N20 G56 G00      X0   Y0   Z100      S1200      F1500      M03      T01 M16
N30 G83 Z80 P32:800 P33:0 P34:52 P36:4 P37:15 P38:1 P39:1
N40 M05 ...
```

Sequence plan

- 1 Switch spindle on (M03, M04) and X and Y axis in rapid traverse position.
- 2 After achieving the X and Y position the Z axis runs on the anticipation plane (P34).
- 3 After achieving the anticipation plane the Z axis with working feed induces itself to
1. drilling depth (P37) on the Z position: $P34 - P37 = 52 - 15 = 37$.
- 4 After achieving 1.drilling depth returns the Z axis in rapid traverse to the anticipation plane.
- 5 Of the anticipation plane in rapid traverse up to the 1. drilling depth plus safety margin (P38).
- 6 With working feed to 2. drilling depth on the Z position: $37 - 11 = 26$ ($11 = 15 - 4$).
- 7 After achieving the 2. drilling depth to the anticipation plane back.
- 8 Of the anticipation plane in rapid traverse up to 2. drilling depth plus safety margin (P38).
- 9 With working feed to the 3. drilling depth on the Z position: $26 - 7 = 19$ ($7 = 11 - 4$).
- 10 After achieving the 3. drilling depth to the anticipation plane back.
- 11 Of the anticipation plane in rapid traverse up to the 3. drilling depth plus safety margin (P38).
- 12 With working feed to 4. drilling depth on the Z position: $19 - 4 = 15$ (P36:4).
- 13 After achieving the 4. drilling depth to the anticipation plane back.
- 14 Of the anticipation plane in rapid traverse up to 4. drilling depth plus safety margin (P38).
- 15 With working feed to 5. drilling depth on the Z position: $15 - 4 = 11$ (P36:4).
- 16 After achieving the 5. drilling depth to the anticipation plane back.
- 17 Of the anticipation plane in rapid traverse up to 5. drilling depth plus safety margin (P38).
- 18 With working feed to 6. drilling depth on the z-position: $11 - 4 = 7$ (P36:4).
- 19 After achieving the 6. drilling depth to the anticipation plane back.
- 20 Of the anticipation plane in rapid traverse up to 6. drilling depth plus safety margin (P38).
- 21 With working feed to 7. drilling depth on the Z position: $7 / 2 = 3,5$.
- 22 After achieving the 7. drilling depth to the anticipation plane back.
- 23 Of the anticipation plane in rapid traverse up to 7. drilling depth plus safety margin (P38).
- 24 With working feed to 8. drilling depth on the Z position: $3,5 - 3,5 = 0$.
- 25 After achieving 8. drilling depth returns the Z axis in rapid traverse to the anticipation plane.

5.3.4 G84 Thread cutting




Figure 5-22

Meaning of the parameters

| | | | |
|-----|--------------------|---|--|
| P31 | balance fodder | P31: 1 | = thread cutting without balance fodder |
| | | P31: 0 or - | = G84 standard cycle (with balance fodder) |
| P32 | thread pitch | | |
| P33 | thread depth | | |
| P34 | anticipation plane | safety margin of the processing upper edge to running around obstacles in the setting axis | |
| P35 | retreat plane | | |

5.3.4 G84 Thread cutting (continued)

Example

N10 ...

N20 G56 G00 X0 Y0 Z100 S1200 F1500 M03 T01 M16


N30 **G84** Z80 **P32:10 P33:20 P34:52** P35:60

N40 M05 ...

Sequence plan

- 1 Switch spindle on (M03, M04) and X and Y axis in rapid traverse position.
- 2 After achieving the X and Y positions the Z axis runs on the anticipation plane.
- 3 After achieving the anticipation plane the Z axis is joined with the spindle axis and the Z axis moves to the drilling depth (P33).
- 4 With the achieving of the drilling depth the spindle rotation is turned around and the spindle reversal time (P30) recalled.
- 5 At process of the retention time the Z axis returns to the anticipation plane (P34).
- 6 With the achieving of the anticipation plane the Z-axis in rapid traverse becomes on the retreat plane (P35) driven and afterwards the spindle switched off (M05).

5.3.5 G85 Drilling with retraction at feed rate

**Meaning of the parameters**

| | | |
|-----|--------------------|---|
| P30 | free cutting time | |
| P32 | drilling feed | |
| P33 | drilling depth | |
| P34 | anticipation plane | safety margin of the processing upper edge |
| P35 | retreat plane | to running around obstacles in the setting axis |

5.3.5 G85 Drilling with retraction at feed rate (continued)

Example

N10 ...

N20 G56 G00 X0 Y0 Z100 S1200 F1500 M03 T01 M16

N30 **G85** Z80 P30:1 P32:800 **P33:0 P34:32**

N40 M05 ...

Sequence plan

- 1 Switch spindle on (M03, M04) and X and Y axis in rapid traverse position.
- 2 After achieving the X and Y positions the Z axis runs in rapid traverse on those anticipation plane (P34).
- 3 After achieving the anticipation plane the Z axis with working feed becomes the drilling depth (P33) moves.
- 4 With the achieving of the drilling depth a programmed free cutting time (P30) is waited for.
- 5 Afterwards retreat in the working feed to anticipation plane and becomes following spindle switched off (M05).

5.4 G86 / G87 / G88 / G89 cycle patterns

The cycle patterns serve for the repeated version of process cycles (boring and milling cycles). Over the programming of certain parameters the points of positioning are described, in which the process cycles are to be executed.

The parameters cover the definition of a target as well as the number of points of positioning. For definition of the target and the points of positioning different programming types can be used.

The partitioning of the cycle patterns takes place on the basis of geometrical criteria:

| | |
|-----|-------------------------------|
| G86 | vector type processing |
| G87 | parallelogram type processing |
| G88 | grid type processing |
| G89 | circle type processing |

The cycle patterns are block by block effective.

The parameter inputs remain against it modal effectively.

In order to avoid over regulation, all parameters are to be reset, which are not used with a programming type.

A compilation of the parameters is listed on the next side.

5.4 G86 / G87 / G88 / G89 cycle patterns (continued)

Parameter for G86 vector type processing

| | |
|------|---|
| P100 | coordinate of the 1. axis (X) |
| P101 | coordinate of the 2. axis (Y) |
| P103 | vector bracket related to the 1. axis (X) |
| P104 | vector length |
| P105 | vector splitting |
| P106 | number of points of positioning |

Parameter for G87 periphery processing of a parallelogram

| Vector 1 | Vector2 | |
|----------|---------|---|
| P100 | P110 | coordinate of the 1. axis (X) |
| P101 | P111 | coordinate of the 2. axis (Y) |
| P103 | P113 | vector bracket related to the 1. axis (X) |
| P104 | P114 | vector length |
| P105 | P115 | vector splitting |
| P106 | P116 | number of points of positioning |

Parameter for G88 grid processing

| Vector 1 | Vector 2 | |
|----------|----------|--|
| P100 | P110 | coordinate of the 1. Axis @@@(x) |
| P101 | P111 | coordinate of the 2. Axis @@@(y) |
| P103 | P113 | vector bracket related to the @@@1.Achse (x) |
| P104 | P114 | vector length |
| P105 | P115 | vector splitting |
| P106 | P116 | number of points of positioning |

Parameter for G89 circle processing

| | |
|------|---|
| P120 | coordinate of the 1. axis (X) of the pitch diameter focal point |
| P121 | coordinate of the 2. axis (Y) of the pitch diameter focal point |
| P122 | circle diameter |
| P123 | start bracket |
| P124 | travel bracket |
| P125 | vector part |
| P126 | number of points of positioning |

5.4 G86 / G87 / G88 G89 cycle patterns (continued)**Messages**

Messages to the cycles have numbers, which start with 8xxx.
A listing is to be found in the paragraph ' 9,9 messages of cycles '.

Messages appear, if

- the target with a programming type by programming of additional parameters multiple is defined and no agreement is achieved.
- the target is not sufficiently determined.

In these cases the program is interrupted.

Therefore all parameters are to be reset, which are not used with a programming type for the definition of the target.

5.4 G86 / G87 / G88 G89 cycle patterns (continued)**Call of process cycles with cycle patterns**

Together with a cycle pattern call a process cycle (boring or milling cycle) can be activated, which is then called after each positioning step in the cycle pattern.

Effectiveness of M functions

Pre path M functions are executed in the starting point A, after path M functions in the target B.

M functions, which are effective within cycles (e.g. M03, M05,...), become for each cycle call pre path or after path actively.

Start the points of positioning

Starting the respective points of positioning effected with G00. Contains the theorem a cycle call, in each point of positioning the cycle is executed. Otherwise an accurate stop (G08) is activated

5.4.1 Vector type processing

Start point and target point with G86




Figure 5-24 A = Start point, B = Target point

Meaning of the parameters

- P100 AB coordinate of the 1. axis (X)
- P101 AB coordinate of the 2. axis (Y)
- P103 vector bracket related to the 1. axis (X)
- P104 vector length
- P105 vector splitting
- P106 number of positioning points

5.4.1 Vector type processing (continued)

Example 1: Programming with AB coordinates P100 and P101 and number of points of positioning

| | | | | | | | | |
|-----|----------------|----------------|------------|--------|--------|---------------|-----|-----|
| N10 | G00 | X20 | Y20 | Z100 | S500 | M03 | T01 | M16 |
| N20 | P100:90 | P101:30 | P103:– | P104:– | P105:– | P106:4 | | |
| N30 | P32:800 | P33:0 | P34:32 | | | | | |
| N40 | G86 | G81 | | | | | | |

Example 2: Programming with vector brackets P103 and vector length P104 and number of points of positioning

| | | | | | | | | |
|-----|------------|------------|----------------|----------------|--------|---------------|-----|-----|
| N10 | G00 | X20 | Y20 | Z100 | S500 | M03 | T01 | M16 |
| N20 | P100:– | P101:– | P103:20 | P104:96 | P105:– | P106:4 | | |
| N30 | P32:800 | P33:0 | P34:32 | | | | | |
| N40 | G86 | G81 | | | | | | |

Example 3: Programming with vector brackets P103 and vector splitting P105 and number of points of positioning

| | | | | | | | | |
|-----|------------|------------|----------------|--------|----------------|---------------|-----|-----|
| N10 | G00 | X20 | Y20 | Z100 | S500 | M03 | T01 | M16 |
| N20 | P100:– | P101:– | P103:20 | P104:– | P105:32 | P106:4 | | |
| N30 | P32:800 | P33:0 | P34:32 | | | | | |
| N40 | G86 | G81 | | | | | | |

5.4.1 Vector type processing (continued)**Process**

| | |
|-----|--|
| N10 | programming of the start point with X and Y |
| N20 | programming of the target point with the parameters P100 and P101 or P103 and P104 or P103 and P105 |
| N30 | programming of the parameters of the process cycle |
| N40 | calls of the cycle pattern and the process cycle |

Sequence of the operation: position first and then process.

Note: not used parameters are to be reset.

5.4.1 Vector type processing (continued)

Programming the start point A

The start point is established by programming the X, Y.. coordinates. If these coordinates have not been programmed the machine stop location coordinates are used as the starting coordinates.

Programming the target point B

Programming mode 1

The target point B is established by programming the X (AB) P100 and Y (AB) P101 coordinates.

$$B_x = A_x + X(AB)$$

$$B_y = A_y + Y(AB)$$

Programming mode 2

The target point B is established by programming the angle P103 and the length of vector P104.

$$X(AB) = P104 * \cos P103$$

$$Y(AB) = P104 * \sin P103$$

Programming mode 3

The target point B is established by programming the angle P103, the vector part P105 and the number of positioning points P106.

For P106 equal to or greater than 2 the following applies:

$$X(AB) = P105 * (P106-1) * \cos P103$$

$$Y(AB) = P105 * (P106-1) * \sin P103$$

For P106=0 and P106=1:

$$X(AB) = P105 * P106 * \cos P103$$

$$Y(AB) = P105 * P106 * \sin P103$$

5.4.1 Vector type processing (continued)

Data analysis

Angel P103

- $\geq 0^\circ$: angle in positive mathematical sense (left-handed rotation)
referred on the positive vector of the 1. axis (X)
- $< 0^\circ$: angle in negative mathematical sense (right-handed rotation)
referred on the positive vector of the 1. axis (X)
- $\geq 360^\circ$: reduction of the angle on smaller 360°

Influence of the planes that are switched on

The sizes X and Y and the angle P103 are plane-oriented.

| Plane | Axis | P103 referred on the positive vector of the axis |
|----------|--------|--|
| G17 (XY) | X Y | X |
| G18 (ZX) | Z X | Z |
| G19 (YZ) | Y Z | Y |

Vector length P104 and vector part P105

Negative values are changed into positive values without indication.

5.4.1 Vector type processing (continued)

Number of positioning points P106

Negative values are changed into positive values.

Non-integer values are round down to the next smaller integer value.

Number of positioning points P106=0

The target point B (from A to B) is approached directly; eventually activated cycles are not executed.

Number of positioning points P106=1

The target point B (from A to B) is approached directly and an eventually activated cycle is executed in the target point.

Number of positioning points P106 and vector part P105

Further identifications for the programming modes 1 and 2 could be the number of positioning points P106 or the vector part P105.

When indicating the vector part P105, the number of positioning points is determined:

$$N = (AB / P105) + 1$$

After this, the vector part is calculated:

$$T' = AB / (P106 - 1)$$

If the calculated number N is an integer number:

$$P105' = P105$$

If the calculated number N is not an integer number:

$$P105' \text{ unequal to } P105$$

The positioning points is executed with the value T'.

5.4.2 G87 Parallelogram type processing

Start and target point with G87




Figure 5-25

Meaning of the parameters

Vector 1 Vector 2

| | | |
|------|------|---|
| P100 | P110 | coordinate of the 1. axis (X) |
| P101 | P111 | coordinate of the 2. axis (Y) |
| P103 | P113 | vector bracket related to the 1. axis (X) |
| P104 | P114 | vector length |
| P105 | P115 | vector part |
| P106 | P116 | number of positioning points |

5.4.2 G87 Parallelogram type processing (continued)

Example 1: Programming with AB coordinates P100, P101 and P110, P111 and number of positioning points

| | | | | | | | | |
|-----|--------------------------|--------------------------|--------------------------|---------------------------------|-------------------------|--------|--------|-----|
| N10 | G00 | X20 | Y20 | Z100 | S500 | M03 | T01 | M16 |
| N20 | P100:90 P114:— | P101:30 P105:— | P110:20 P115:— | P111:40 P106:4 | P103:— P116:3 | P113:— | P104:— | |
| N30 | P32:800 | P33:0 | P34:32 | | | | | |
| N40 | G87 | G81 | | | | | | |

Example 2: Programming with vector brackets P103, P113 and vector length P104, P114 and number of positioning points

| | | | | | | | | |
|-----|--------------------------|------------------|------------------|-------------------------|---------------------------------|----------------|----------------|-----|
| N10 | G00 | X20 | Y20 | Z100 | S500 | M03 | T01 | M16 |
| N20 | P100:— P114:46 | P101:— P105:— | P110:— P115:— | P111:— P106:4 | P103:20 P116:3 | P113:60 | P104:96 | |
| N30 | P32:800 | P33:0 | P34:32 | | | | | |
| N40 | G87 | G81 | | | | | | |

Example 3: Programming with vector brackets P103, P113 and vector splitting P105, P115 and number of positioning points

| | | | | | | | | |
|-----|------------------|--------------------------|--------------------------|-------------------------|---------------------------------|----------------|--------|-----|
| N10 | G00 | X20 | Y20 | Z100 | S500 | M03 | T01 | M16 |
| N20 | P100:— P114:— | P101:— P105:32 | P110:— P115:23 | P111:— P106:4 | P103:20 P116:3 | P113:60 | P104:— | |
| N30 | P32:800 | P33:0 | P34:32 | | | | | |
| N40 | G87 | G81 | | | | | | |

5.4.2 G87 Parallelogram type processing (continued)**Process**

| | |
|-----|---|
| N10 | programming of the start point with X and Y |
| N20 | programming of the target point with the parameters P100, P110 and P101, P111 or P103, P113 and P104, P114 or P103, P113 and P105, P115 |
| N30 | programming of the parameters of the process cycle |
| N40 | calls of the cycle pattern and the process cycle |

Sequence of the operation: first position and then process.

Sequence of processing: for and return trip always
first vector 1 and then vector 2

Note: not used parameters are to be reset

5.4.2 G87 Parallelogram type processing (continued)

Programming of the start point A

The start point A is determined by programming the coordinates X, Y..

If the coordinates are not programmed, the coordinates of the machine location are used as start coordinates.

Programming of the target points B and C

Programming mode 1

The target points B and C are determined by programming the coordinates X (AB) P100 / Y (AB) P101 and X (AC) P110 / Y (AC) P111.

Target point B $B_x = A_x + X(AB)$
 $B_y = A_y + Y(AB)$

Target point C $C_x = A_x + X(AC)$
 $C_y = A_y + Y(AC)$

Programming mode 2

The target points B and C are determined by programming the angles P103 / P113 and vector length P104 / P114.

Target point B $X(AB) = P104 * \cos P103$
 $Y(AB) = P104 * \sin P103$

Target point C $X(AC) = P114 * \cos P113$
 $Y(AC) = P114 * \sin P113$

Programming mode 3

The target points B and C are determined by programming the angles P103 / P113, the vector parts P105 / P115 and number of positioning points P106 / P116.

For P106 / P116 >= 2:

Point B $X(AB) = P105 * (P106-1) * \cos P103$
 $Y(AB) = P105 * (P106-1) * \sin P103$

Point C $X(AC) = P115 * (P116-1) * \cos P113$
 $Y(AC) = P115 * (P116-1) * \sin P113$

For P106 / P116 = 0 and P106 / P116 = 1 :

Point B $X(AB) = P105 * P106 * \cos P103$
 $Y(AB) = P105 * P106 * \sin P103$

Point C $X(AC) = P115 * P116 * \cos P113$
 $Y(AC) = P115 * P116 * \sin P113$

5.4.2 G87 Parallelogram type processing (continued)

Data evaluation

Angle P103, P113

- $\geq 0^\circ$: angle in positive mathematical sense (left-handed rotation)
referred on the positive vector of the x-axis
- $< 0^\circ$: angle in negative mathematical sense (right-handed rotation)
referred on the positive vector of the x-axis
- $\geq 360^\circ$: reduction of the angle on smaller 360°

Influence of the plane that is switched on:

The sizes X and Y and the angle P103, P113 are plane-oriented.

| Plane | Axis | P103, P113 referred on the positive vector of the axis |
|----------|--------|--|
| G17 (XY) | X Y | X |
| G18 (ZX) | Z X | Z |
| G19 (YZ) | Y Z | Y |

Vector length P104, P114 and vector part P105, P115

Negative values are changed into positive values without indication.

5.4.2 G87 Parallelogram type processing (continued)**Number of positioning points P106, P116**

Negative values are changed into positive values.

Non-integer values are round down to the next smaller integer value.

Number of positioning points P106, P116 = 0

The target point B / C (from A to B / C) are approached directly; eventually activated cycles are not executed.

Number of positioning points P106, P116 = 1

The target points B / C (from A to B / C) are approached directly and an eventually activated cycle is executed in the target point.

Number of positioning points P106, P116 and vector part P105, P115

Further identifications for the programming modes 1 and 2 could be the number of drilling holes P106, P116 or the vector part P105, P115.

When indicating the vector part P105, P115, the number of drilling holes is determined:

$$P106, P116 = (AB / P105, P115) + 1$$

After this, the vector part is calculated:

$$P105', P115' = AB / (P106, P116 - 1)$$

If the calculated number P106, P116 is an integer number:

$$P105', P115' = P105, P115$$

If the calculated number P106, P116 is not an integer number:

$$P105', P115' \text{ unequal to } P105, P115$$

The drilling pattern is executed with the value P105', P115'.

5.4.3 G88 Grid type processing

Start and target point at G88




Figure 5-26

Meaning of the parameters

Vector 1 Vector 2

| | | |
|------|------|---|
| P100 | P110 | coordinate of the 1. axis (X) |
| P101 | P111 | coordinate of the 2. axis (Y) |
| P103 | P113 | vector bracket related to the 1. axis (X) |
| P104 | P114 | vector length |
| P105 | P115 | vector part |
| P106 | P116 | number of positioning points |

5.4.3 G88 Grid type processing (continued)

Example 1: Programming with AB coordinates P100, P110 und P101, P111 and number of positioning points

| | | | | | | | | |
|-----|--------------------------|--------------------------|--------------------------|---------------------------------|-------------------------|--------|--------|-----|
| N10 | G00 | X20 | Y20 | Z100 | S500 | M03 | T01 | M16 |
| N20 | P100:90 P114:– | P101:30 P105:– | P110:20 P115:– | P111:40 P106:4 | P103:– P116:3 | P113:– | P104:– | |
| N30 | P32:800 | P33:0 | P34:32 | | | | | |
| N40 | G88 | G81 | | | | | | |

Example 2: Programming with vector brackets P103, P113 and vector length P104, P114 and number of positioning points

| | | | | | | | | |
|-----|--------------------------|------------------|------------------|-------------------------|---------------------------------|----------------|----------------|-----|
| N10 | G00 | X20 | Y20 | Z100 | S500 | M03 | T01 | M16 |
| N20 | P100:– P114:46 | P101:– P105:– | P110:– P115:– | P111:– P106:4 | P103:20 P116:3 | P113:60 | P104:96 | |
| N30 | P32:800 | P33:0 | P34:32 | | | | | |
| N40 | G88 | G81 | | | | | | |

Example 3: Programming with vector brackets P103, P113 and vector splitting P105, P115 and number of positioning points

| | | | | | | | | |
|-----|------------------|--------------------------|--------------------------|-------------------------|---------------------------------|----------------|--------|-----|
| N10 | G00 | X20 | Y20 | Z100 | S500 | M03 | T01 | M16 |
| N20 | P100:– P114:– | P101:– P105:32 | P110:– P115:23 | P111:– P106:4 | P103:20 P116:3 | P113:60 | P104:– | |
| N30 | P32:800 | P33:0 | P34:32 | | | | | |
| N40 | G88 | G81 | | | | | | |

5.4.3 G88 Grid type processing (continued)**Process**

- N10 programming of the start point with X and Y
- N20 programming of the target point with the parameters
P100, P110 and P101, P111 or P103, P113 and P104, P114 or P103, P113 and
P105, P115
- N30 programming of the parameters of the process cycle
- N40 calls of the cycle pattern and the process cycle

Sequence of the operation: first position and then process.

Sequence of processing: first with journey there first vector 1 completely
and afterwards the first position on vector 2,

then with return trip vector 1 completely
and afterwards the next position on vector 2,

then again with journey there vector 1 completely etc.
until the final position on vector 2 achieves
and the processing of vector 1 is executed

thereafter the initial position is started.

Note: not used parameters are to be reset

5.4.3 G88 Grid type processing (continued)

Programming the start point A

The start point A is determined by programming the coordinates X, Y...

If the coordinates are not programmed, the coordinates of the machine location are used as starting coordinates.

Programming of the target points B and C

Programming mode 1

The target points B and C are determined by programming the coordinates X (AB) P100, Y (AB) P101 and X (AC) P110, Y (AC) P111.

Target point B $B_x = A_x + X(AB)$
 $B_y = A_y + Y(AB)$

Target point C $C_x = A_x + X(AC)$
 $C_y = A_y + Y(AC)$

Programming mode 2

The target points B and C are determined by programming the angles P103, P113 and vector length P104, P114.

Target point B $X(AB) = P104 * \cos P103$
 $Y(AB) = P104 * \sin P103$

Target point C $X(AC) = P114 * \cos P113$
 $Y(AC) = P114 * \sin P113$

Programming mode 3

The target points B and C are determined by programming the angles E1 / E2, the vector parts T1 / T2 and number of drilling holes N1 / N2.

For $N \geq 2$:

Point B $X(AB) = P105 * (P106-1) * \cos P103$
 $Y(AB) = P105 * (P106-1) * \sin P103$

Point C $X(AC) = P115 * (P116-1) * \cos P113$
 $Y(AC) = P115 * (P116-1) * \sin P113$

For $P106, P116 = 0$ and $P106, P116 = 1$:

Point B $X(AB) = P105 * P106 * \cos P103$
 $Y(AB) = P105 * P106 * \sin P103$

Point C $X(AC) = P115 * P116 * \cos P113$
 $Y(AC) = P115 * P116 * \sin P113$

5.4.3 G88 Grid type processing (continued)

Data evaluation

Angle P103, P113

- $\geq 0^\circ$: angle in positive mathematical sense (left-handed rotation)
referred on the positive vector of the x-axis
- $< 0^\circ$: angle in negative mathematical sense (right-handed rotation)
referred on the positive vector of the x-axis
- $\geq 360^\circ$: reduction of the angle on smaller 360°

Influence of the plane that is switched on:

The sizes X and Y and the angle P103, P113 are plane-oriented.

| Plane | Axis | P103, P113 referred on the positive vector of the axis |
|----------|--------|--|
| G17 (XY) | X Y | X |
| G18 (ZX) | Z X | Z |
| G19 (YZ) | Y Z | Y |

Vector length P104, P114 and vector part P105, P115

Negative values are changed into positive values without indication.

5.4.3 G88 Grid type processing (continued)

Number of drilling holes P106, P116

Negative values are changed into positive values.

Non-integer values are round down to the next smaller integer value.

Number of drilling holes P106, P116 = 0

The target points B / C (from A to B / C) are approached directly; eventually activated cycles are not executed.

Number of drilling holes P106, P116 = 1

The target points B / C (from A to B / C) are approached directly and an eventually activated cycle is executed in the target point.

Number of drilling holes P106, P116 and vector part P105, P115

Further identifications for the programming modes 1 and 2 could be the number of drilling holes P106, P116 or the vector part P105, P115.

When indicating the vector part P105, P115, the number of drilling holes is determined:

$$P106, P116 = (AB / P105, P115) + 1$$

After this, the vector part P105, P115 is calculated:

$$P105', P115' = AB / (P106, P116 - 1)$$

If the calculated number P106, P116 is an integer number:

$$P105', P115' = P105, P115$$

If the calculated number P106, P116 is not an integer number:

$$P105', P115' \text{ unequal to } P105, P115$$

The drilling pattern is executed with the value P105', P115'.

5.4.4 G89 Circle type processing

Start and target point at G88




Figure 5-27

Meaning of the parameters

| | |
|------|---|
| P120 | Coordinate of the 1. axis (X) of the positioning points |
| P121 | Coordinate of the 2. axis (Y) of the positioning points |
| P122 | Pitch circle diameter |
| P123 | Start angle |
| P124 | Travel angle |
| P125 | Vector part |
| P126 | Number of positioning points |

5.4.4 G89 Circle type processing (continued)

Example 1: Programming with centre coordinates P120, P121, circle diameter P122, start brackets P123 and travel bracket P124 and number of positioning points

| | | | | | | | |
|-----|----------------|----------------|-----------------|----------------|-----------------|---------|---------------|
| N10 | G00 M03 | Z100 T01 | S500 M16 | | | | |
| N20 | P120:70 | P121:20 | P122:100 | P123:18 | P124:120 | P125:-- | P126:5 |
| N30 | P32:800 | P33:0 | P34:32 | | | | |
| N40 | G89 | G81 | | | | | |

Example 2: Programming with centre coordinates P120, P121, circle diameter P122, start brackets P123 and vector part P125 and number of positioning points

| | | | | | | | |
|-----|----------------|----------------|-----------------|----------------|---------|----------------|---------|
| N10 | G00 M03 | Z100 T01 | S500 M16 | | | | |
| N20 | P120:70 | P121:20 | P122:100 | P123:18 | P124:-- | P125:30 | P126:-- |
| N30 | P32:800 | P33:0 | P34:32 | | | | |
| N40 | G89 | G81 | | | | | |

5.4.4 G89 Circle type processing (continued)**process**

- N10 programming of the start point with P120, P121, P122 and P123
- N20 programming of the target point with the parameters
P120, P121, P122, P123 and P124 or P120, P121, P122, P123 and P125
- N30 programming of the parameters of the process cycle
- N40 calls of the cycle pattern and the process cycle

Sequence of the operation: first position and then process.

Sequence of processing: dependent on the programmed type of interpolation
G00, G01 or G02, G03 become the particulars
positions straight linear or circular interpolates started.

Note: not used parameters are to be reset

5.4.4 G89 Circle type processing (continued)

Programming the start point A

The starting point A always has to be determined by programming identifications at G89, i.e. the pitch circle centre point P120, P121, the pitch circle radius P122/2 and the starting angle P123.

Programming the target point B

Programming mode 1

The target point B is determined by programming the travel angle P124.

$$B_x = P120 + (P122/2) * \cos(P123 + P124)$$

$$B_y = P121 + (P122/2) * \sin(P123 + P124)$$

Programming mode 2

The target point is determined by programming the number of positioning points P126 and the vector part P125.

$$B_x = P120 + (P122/2) * \cos(P123 + (P126-1) * P125)$$

$$B_y = P121 + (P122/2) * \sin(P123 + (P126-1) * P125)$$

$$P124 = (P126-1) * P125$$

5.4.4 G89 Circle type processing (continued)

Data evaluation

Angle P123

- $\geq 0^\circ$: angle in positive mathematical sense (left-handed rotation)
referred on the positive vector of the x-axis
- $< 0^\circ$: angle in negative mathematical sense (right-handed rotation)
referred on the positive vector of the x-axis
- $\geq 360^\circ$: reduction of the angle on smaller 360°

Influence of the plane that is switched on:

The sizes X and Y and the angle P123 are plane-oriented.

| Plane | Axis | P123 referred on the positive vector of the axis |
|----------|--------|--|
| G17 (XY) | X Y | X |
| G18 (ZX) | Z X | Z |
| G19 (YZ) | Y Z | Y |

Vector part P125

Negative values are changed into positive values without indication.

5.4.4 G89 Circle type processing (continued)**Number of positioning points P126**

Negative values are changed into positive values.

Non-integer values are round down to the next smaller integer value.

Number of positioning points $P126 = 0$

The target point B (from A to B) is approached directly; eventually activated cycles are not executed.

Number of positioning points $P126 = 1$

The target point B (from A to B) is approached directly and an eventually activated cycle is executed in the target point.

Number of positioning points P126 and vector part P125

Further identifications for the programming modes 1 and 2 could be the number of positioning points P126 or the vector part P125.

When indicating the vector part P125, the number of positioning points P126 is determined:

$$P126 = (P124 / P125) + 1$$

After this, the vector part is calculated:

$$P125' = P124 / (P126 - 1)$$

If the calculated number P126 is an integer number:

$$P125' = P125$$

If the calculated number N is not an integer number:

P125' unequal to P125

The drilling pattern is executed with the value P125'.

5.4.4 G89 Circle type processing (continued)

Starting the points of positioning (G89)

Starting of the points of positioning depends on the programmed type of interpolation.

G00 or G01 actively




Figure 5-28

The positions (A1, A2, A3 and B) are started with G00.

The sign of the travel bracket P124 or, if this does not indicated, the sign of the vector part P125 determines, whether the circle is anti-clockwise rotation or is clockwise rotation processed:

| | |
|-------------------------------|--------------------------|
| Positive sign of the bracket: | anti-clockwise rotation, |
| Minus sign of the bracket: | clockwise rotation. |

5.4.4 G89 Circle type processing (continued)

G02 or G03 actively




Figure 5-29

The positioning points are started with G02 or G03 and max. programmable feed speed.

Two cases are to be differentiated:

The travel bracket is positive (anti-clockwise rotating)

With G03 also the positioning direction is positive.

With G02 the positioning direction is negative (moving in opposite directions to the travel bracket).

The travel bracket is negative (clockwise rotatingly)

With G02 also the positioning direction is positive.

With G03 the positioning direction is negative (moving in opposite directions to the travel bracket).

5.5 Customer specific cycles

A cycle is a program that generates certain repeated sequences.

For user-specific cycles, these sequences are defined in a Z-program.

Example: Z1001
N10 ...
.
.
N40 P500 : P500+1
.
.
N60 M30

The defined cycle can be started then in a machining program with a G-function.
The G-function must have the same number as the Z-program.

Example: P2000

N10 ...
.
.
N60 P500 : 2 G1001
.
.
N90 M30

The G-function numbers can be selected arbitrarily except those numbers that are already reserved for other functions.

Input variables can be transmitted to the Z-program with parameters. The parameter numbers P500 to P4999 are free for the user. P0 to P499 is reserved for BWO-cycles.
If the BWO-cycles are not used, they are also free for the user.

Additional functions to the operating system

Additional functions could be implemented with a DLL (Dynamic Link Library) that is written in programming language C.